




Redacted as Non Responsive (Other Sites)









Proposed Next Steps

Redacted as Non Responsive (Other Sites)

[DateTime]





The Red Oaks neighborhood in Andover, MN outlined in blue with WDE landfill outlined in yellow. Investigation 7/1/2021 1,4-dioxane result of 1.1 ppb at single home Investigation expands to W and S 1,4-dioxane detected in SE of neighborhood,

Communications

- 2 public meetings
- 2 office hours sessions
- Many newsletter articles
- Website updates
- Too many citizen calls to count

PFAS detected at most homes

Citizen Concerns


- Health of residents and their families
- Property value decrease
- Costs of municipal water
- Losing private wellsBottled water
- Sampling


The South Andover Superfund

Site to the South of Bunker


Lake Boulevard.








Show the lack of a link between the two 1-4 dioxane plumes




Bunker Lake Blvd Sample Points

- Groundwater flow direction is North according to some historical documents
- SB-2 1,4-dioxane result 840ppb in deep sample
- Low amounts 1,4 dioxane shallow and medium samples at SB-2 and deep sample at SB-3
- PFOS and PFOA exceed drinking water criteria at SB1, 2, 3, and 4 at shallow and mid-depths
- South Andover NPL Site never tested for either 1,4 dioxane or PFAS





Red Oaks Next Steps


- Recent data indicates WDE landfill is not the 1,4DX source therefore Closed Landfill funds can no longer be used – DX transitioning to Superfund
 - 1,4 DX Source Investigation
 - Municipal Water Installation
 - * \$12.1 Million Needed
 - Future Sampling
 - PFAS expansion to the Western edge of Red Oaks and continuing West
 - 1,4-dioxane and PFAS in South Andover SF Site
- EPA's Role?














	Josyln Site	
Redacted as Non	Responsive (Other Sit	tes)















	Arrowhead Refinery S	ite
Redacted as	Non Responsiv	ve (Other Sites)










Highway 100/Co. Rd. 3 Site	
Redacted as Non Responsive (Other Sites)	
[DateTime]	37














MPCA Superfund Leadership Team

- Jamie Wallerstedt | Remediation Division Director
- Tom Higgins | Superfund Section Manager
- Crague Biglow | Superfund Supervisor / SLRAOC
- Tim Grape | Superfund Supervisor
- Michele Mabry | Site Assessment Supervisor
- Jeff Thuma | Program Administrator & Contract Manager

[DateTime]

Optional Tagline Goes Here | mn.gov/websiteurl

44

